

National Transportation Safety Board Aviation Accident Data Summary

Location: DELTA, UT Accident Number: DEN82FA020

Date & Time:01/17/1982, 1435 MSTRegistration:N91TWAircraft:PIPER PA-31TInjuries:3 Minor

Flight Conducted Under: Part 91: General Aviation - Personal

Analysis

APPROXIMATELY 1/2 MI FROM THE ARPT AFTER TAKEOFF, THE PLT NOTICED THE LEFT FRONT BAGGAGE DOOR PARTLY OPEN & MADE A LEFT TURN BACK TOWARD THE AIRSTRIP. AFTER THE TURN, THE BAGGAGE DOOR CAME COMPLETELY OPEN, THE LEFT WING DROPPED IMMEDIATELY & THE ACFT STALLED. THE PLT ADDED FULL POWER & LOWERED THE NOSE. WHEN HE RAISED THE NOSE NEAR THE GROUND, THE ACFT SHUDDERED & CRASHED. TWO RESCUE PERSONNEL, BOTH CERTIFICATED PILOTS, ARRIVED SHORTLY AFTER THE ACCIDENT & FOUND THE NOSE BAGGAGE DOOR IN THE UNLOCKED POSITION WITH THE BAYONET PINS RETRACTED. A PIPER REPRESENTATIVE STATED THAT IF THE LEFT SIDE NOSE BAGGAGE DOOR OF A PA-31T OPENED IN FLT THERE WOULD BE THE LIKELIHOOD OF AN INTERRUPTION TO THE SMOOTH AIRFLOW THROUGH THE PROP, POSSIBLY REDUCING THE THRUST PRODUCED BY THE BLADES.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Findings

- 1. (F) DOOR, CARGO/BAGGAGE UNLOCKED
- 2. (F) AIRCRAFT PREFLIGHT INADEQUATE PILOT IN COMMAND
- 3. (F) DOOR, CARGO/BAGGAGE OPEN
- 4. (F) PRECAUTIONARY LANDING PERFORMED PILOT IN COMMAND
- 5. (F) AIRCRAFT PERFORMANCE DETERIORATED
- 6. (C) AIRSPEED NOT MAINTAINED PILOT IN COMMAND
- 7. STALL INADVERTENT PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Pilot Information

Certificate:PrivateAge:55Airplane Rating(s):Multi-engine Land; Single-engine LandInstrument Rating(s):AirplaneOther Aircraft Rating(s):Instructor Rating(s):NoneFlight Time:4000 hours (Total, all aircraft), 520 hours (Total, this make and model)

Aircraft and Owner/Operator Information

PIPER N91TW Aircraft Make: Registration: Model/Series: **PA-31T PA-31T Engines:** 2 Turbo Prop Operator: **DERRAL CHRISTENSEN Engine Manufacturer:** P & W Operating Certificate(s) **Engine Model/Series:** PT6A-28 Held:

Flight Conducted Under: Part 91: General Aviation - Personal

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day	
Observation Facility, Elevation:	DTA, 0 ft msl	Weather Information Source:	Unknown	
Lowest Ceiling:	Unknown / 0 ft agl	Wind Speed/Gusts, Direction:	8 knots / , 220 $^{\circ}$	
Temperature:	50°C	Visibility	50 Miles	
Precipitation and Obscuration:				
Departure Point:	DELTA, UT	Destination: LAS VEGAS, NV ((LAS)	

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage: Destroyed
Passenger Injuries:	2 Minor	Aircraft Fire: On-Ground
Ground Injuries:	N/A	Aircraft Explosion: On-Ground
Latitude, Longitude:		

Administrative Information

Investigator In Charge (IIC):	Adopted Date: 01/17/1983
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .

Page 2 of 3 DEN82FA020

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

